


SAFETY CERTIFICATE


The Building of North Star Public School Upper Dattal, Tel. Palampur Distt. Kangra (H.P) was inspected by the undersigned alongwith Junior Engineer of Ghar Section on dated 05.10.2021. It has been observed that no earthquake resistant provisions have been adopted for this building and no structural drawings approved by the competent Govt. certified Engineer have been produced at the time of inspection. More over no assistance was taken from PWD for constructing the building. This structure is a non-engineered structure. Hence the structural safety of this building cannot be ensured specifically from earthquake resistance point of view. This department will not be responsible for any type of loss of life and property etc., if this structure fail under any circumstances.

However, as per visual inspection the building has been found safe at present only. No Officer/Official of this office will attend plea in any Hon'ble court of Law in case of any dispute. This certificate is valid for the session 2022-27

Place: - Palampur

Dated:- 06.10.2021


Assistant Engineer,
Palampur Sub-Division,
HP.PWD Palampur.


Executive Engineer,
Palampur Division,
HP.PWD Palampur